# UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 7,071,552 B2

APPLICATION NO.: 10/813187

Page 1 of 1

DATED INVENTOR(S)

: July 4, 2006 : Ravi et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 1

Line 35, "FIG. 3 is ..." should read --FIGS. 3A and 3B are...--.

Line 38, "FIG. 4 is..." should read --FIGS. 4A and 4B are...-.

Line 49, "...FIGS. 2 and 4, ..." should read --...FIGS. 2 and 4A-4B, ...-.

## Column 2

Line 53, "...liquid-conducting passages 32..." should read --...liquid-conducting passages 30...--.

### Column 3

Line 28, "...fluid inlet 38..." should read --...liquid inlet 38...--.

#### Column 4

Line 42, "...liquid flow tube 32..." should read --...liquid feed tube 32...-.

## Column 5

Lines 14 & 16, "...PCB 92..." should read --...PCB 94...-.

Lines 15-16, "...IC package 12..." should read --...IC package 92...--.

Signed and Sealed this

Twenty-seventh Day of May, 2008

JON W. DUDAS
Director of the United States Patent and Trademark Office